

Date: 13.04.2023

**PKG2/C3/ICB/TNUHP/ JICA/TNMSC/ENGG/ 2022, Dt. 13.07.2022**

**for 1 no. of C-Arm machine (Lot/Contract no.1), 4 Nos. Digital Mobile X-ray (Lot/Contract no.2) and 1 no. of Digital X-ray (Lot/Contract no.3) for Secondary care hospitals under JICA Component 3.2**  
**RESULT OF EVALUATION**

Sl. No.	Equipment Details	Technical responsiveness	Commercial responsiveness	Remarks/Reasons for rejection
<b>C-Arm machine (Lot/Contract no.1) (Qty.: 1 no.)</b>				
1.	M/s Allengers Medical Systems, Chandigarh <b>Make:</b> Allengers <b>Model:</b> HF-59 plus <u>Flat panel detector:</u> Amorphous Silicon (A-Si) with Cesium Iodide (CSi).	Responsive	Responsive	—
2.	M/s Trivitron Healthcare Pvt. Ltd., Chennai <b>Make:</b> Kiran Medical Systems (A division of Trivitron Healthcare Pvt. Ltd.,) <b>Model:</b> Elite/Infinity (Brand: Kiran)	Responsive	<b>Responsive subject to assessment of performance of 19 nos. C-Arm supplied earlier and confirmation of satisfactory performance by the independent Expert Committee and acceptance of the report by the Competent Authority</b>	1) Frequent breakdown were reported in the 19 nos. of earlier order procurement under PKG1/ICB/TNUHP/JICA/C 2/ RAD/TNMSC/ENGG/2020-3 Dt. 12.04.2021, which is under investigation by independent committee. 2) The frequent breakdown issues were also found in the C-Arm procured directly by the hospitals at Thoothukudi, Tirunelveli and Salem, as per the service reports.

Sl. No.	Equipment Details	Technical responsiveness	Commercial responsiveness	Remarks/Reasons for rejection
<b>Digital Mobile X-ray (Lot/Contract no.2) (Qty.: 4 nos.)</b>				
1.	M/s Allengers Medical Systems, Chandigarh  <b>Make:</b> Allengers  <b>Model:</b> Mars-32 DR  Flat panel detector: Amorphous Silicon (A-Si) with Cesium Iodide (CSi).	Responsive	Responsive	—
2.	M/s Carestream Health India Pvt. Ltd., Chennai  <b>Make:</b> Carestream Health Inc., USA  <b>Model:</b> DRX-Revolution plus with 3543 detector	Non-Responsive	Non-Responsive	<p><u>Non-complying technical points:</u></p> <p><b>3. X-ray tube:</b></p> <p><u>3.3 The anode speed shall be atleast 8,000 rpm: In the product catalogue indicated 50 Hz (2,700 rpm) and 60 Hz (3,200 rpm).</u></p> <p><b>8. Miscellaneous:</b></p> <p><u>8.8 Motorized tilting of bucky shall be possible: Motorized wall stand with manual bucky tilting only available.</u></p> <p><u>Commercial points:</u></p> <p>Despite requesting the bidder for clarifications on the following points in email dt. 13.12.2022, 21.12.2022 and</p>

Sl. No.	Equipment Details	Technical responsiveness	Commercial responsiveness	Remarks/Reasons for rejection
				<p>23.12.2022, the bidder did not furnish the below indicated documents:</p> <p>a) Duly attested copy of License if any, approved by the concerned Licensing Authority. (ITB 23.1f(ix))</p> <p>b) <b><u>Form EXP 3:</u></b>  <b>Production capacity</b> for Manufacturer/ Manufacturer bidder and <b>Sales capacity</b> for Non - Manufacturer bidder:</p> <p>c) <b><u>Form FIN-3:</u></b>  The Bidder shall demonstrate that it has access to, or has available, liquid assets, unencumbered real assets, lines of credit, and other financial means (independent of any contractual advance payment) sufficient to meet the cash flow requirements for Manufacturer/ Manufacturer Bidder and Non-Manufacturer</p>

Sl. No.	Equipment Details	Technical responsiveness	Commercial responsiveness	Remarks/Reasons for rejection
				<p>Bidder for the subject contract(s) net of the Bidders other commitments.</p> <p>d) <b><u>Form EXP-2:</u></b></p> <p>Specific experience for Manufacturer/Manufacturer bidder and Non - Manufacturer bidder:</p> <p>e) <b><u>Form CON:</u></b></p> <p>The bidder should disclose instance of previous past performance that may have resulted into adverse actions taken against the bidder during the last five years. (ITB 23.1f (xvi))</p> <p>f) Unpriced price schedule indicating the list of Goods/Equipment quoted.</p> <p>g) In case of critical equipment, a certificate from the</p>

Sl. No.	Equipment Details	Technical responsiveness	Commercial responsiveness	Remarks/Reasons for rejection
				<p>supplier/manufacturer to the effect that the equipment does not have any capability to remotely observe or access. If called for by the purchaser a verification and certificate of this claim from a 3<sup>rd</sup> party inspection agency. (ITB 23.1f(xvii))</p> <p>h) Confirmation that all facilities exist with the bidder (or manufacturer, as applicable) in its factory for inspection and testing and these can be accessed by the Purchaser or its representative for inspection. (ITB 23.1 f (xv))</p>
<b>Digital X-ray (Lot/Contract no.3) (Qty.: 1 no.)</b>				

Sl. No.	Equipment Details	Technical responsiveness	Commercial responsiveness	Remarks/Reasons for rejection
1.	M/s Allengers Medical Systems, Chandigarh  <b>Make:</b> Allengers  <b>Model:</b> Mars 80	Responsive	Responsive	—
2.	M/s Trivitron Healthcare Pvt. Ltd., Chennai  <b>Make:</b> Kiran Medical Systems (A division of Trivitron Healthcare Pvt. Ltd.,)  <b>Model:</b> Uitysys-82 (Brand: Kiran)  <u>(i) X-ray tube:</u> Varex, USA  <u>(ii) Digital detector:</u> Fixed type  <u>(iii) Flat panel detector:</u> Pax Scan 4343R v3  <u>(iv) Dual detectors:</u> Table & Vertical Bucky (Varex, USA)	<b>Non-Responsive</b>	Responsive	<u>Non-Complying technical point:</u>  The certificate Ente Certificazione Macchine (ECM) is not in accordance with the European CE certificate. Also in that certificate it was clearly indicated that <u>this document cannot replace the EC declaration of conformity.</u>

Sd/-

General Manager (E)