

## RESULT OF EVALUATION

**Tender for fixing Rate Contract for the Supply & Installation of  
Video Laryngoscope to various Government Institutions.  
Tender No. E884/SCOPE/RC/TNMSC/ENGG/2022, DT:08.11.2022**

**Equipment:** Video Laryngoscope with disposable blades.

Sl. No	Bidders Quoted	Model/ Make	Responsiveness		Reason for rejection / Remarks
			Technical evaluation report	Commercial evaluation report	
1	M/s. RL Health Care	VL3D Hugemed/ Hugemed	Non-Responsive	Responsive	<b>Technical:</b> As per specialist report the model is not meeting. 1.Height of blade should be – 13mm (non-channelled) ,18mm (channelled) or more.
2	M/s. Sandor Medicaids Pvt. Ltd	SANVL3/ Shenzen Hugemed Medical	Non-Responsive	Non-Responsive	<b>Technical:</b> As per specialist report the model is not meeting. 1.Height of blade should be – 13mm (non-channelled), 18mm (channelled) or more. <b>Commercial:</b> -Not furnished PO, Installation report as per tender requirements despite given by chance.
3	M/s. St. Luke Med Devices Pvt. Ltd.	KVL KIT3/ Ambu King Vision Video Laryngoscope	Responsive	Responsive	-----

**Equipment:** Video Laryngoscope with re-useable and autoclavable blades

Sl. No	Bidders Quoted	Model/ Make	Responsiveness		Reason for rejection / Remarks
			Technical evaluation report	Commercial evaluation report	
1	M/s. Alan Medical and Laboratory products	SC-01/Medicam	Non responsive	Responsive	<p><b>Technical:</b> As per specialist report the model is not meeting. 1.It should have power source-3AAA batteries with 250 mins of usage/rechargeable battery. 2.It has wired bulb component to be attached each time.</p>
2	M/s. RL Health Care	S-VL-R-Video Laryngoscope with reuseable blades/Senor endo Medi-Tech Inc	Responsive	Responsive	-----
3	M/s. Sandor Medicaids Pvt. Ltd.	SANVL3/ Shenzen	Non Responsive	Non Responsive	<p><b>Technical:</b> As per specialist report the model is not meeting. 1. Required a standard adult airway and miler blades with titanium handles with integrated camera chips and LED light illumination.</p> <p><b>Commercial:</b> 1.Not furnished PO, Installation report as per tender requirements despite given by chance.</p>