

06.12.2023

RESULTS OF EVALUATION

TENDER NO. E863/ASS/NHM/TNMSC/ENGG/2022, DT.23.08.2022.

Sch. 1: Automatic Slide Stainer:

S.N.	NAME OF THE FIRM	TECHNICAL EVALUATION	COMMERCIAL EVALUATION REPORT	REASONS FOR NON RESPONSIVENESS
1	M/s. K.k. Allianza Model : MSS-LS Make : Medimeas Instruments, Ambala	<i>Not Demonstrated despite given chance</i>	Non-Responsive	1. Not Demonstrated 2. Not meeting the requirement of Annual manufacturing capacity of 144 nos.
2	M/s. Vision Diagnostic India Pvt. Ltd. Model: Gemini AS Make & Branding: Epreia (Shandon Diagnostic Ltd.) previously known as Thermo Fisher Scientific, UK.	Responsive on Physical Demo	Responsive	-
3	M/s. York Scientific Industries Pvt. Ltd. Model : LSM-520 Make : Unimeditrek	Non-Responsive on Physical Demo	Responsive	1. The instrument is not compact and occupies more space. 2. The on board controls are not satisfactory. Return option is not convincing. 3. Return option is not satisfactory. 4. Return option is not proper 5. The information provided in the manual does not cover instrument details and its working procedure. 6. This was the same case with the machine supplied by the manufacturer M/s. Unimeditrek earlier, as the details provided in

S.N.	NAME OF THE FIRM	TECHNICAL EVALUATION	COMMERCIAL EVALUATION REPORT	REASONS FOR NON RESPONSIVENESS
				the user manual was not sufficient to operate the machine effectively.

Sch. 2. Grossing Station:

S.N.	NAME OF THE FIRM	TECHNICAL EVALUATION	COMMERCIAL EVALUATION REPORT	REASONS FOR NON RESPONSIVENESS
1	M/s. Apzem India Engineering Model : DD6000E Make : Apzem	Responsive on physical demonstration	Responsive	-
2	M/s. York Scientific Industries Pvt. Ltd. Model : YSI-222EX Make : Yorco	Non Responsive on physical demonstration	Responsive	1. Not reaching appropriate height. 2. Very cramped work space. Too difficult to clean and maintain 3. Drainage system too complicated. Multiple levels of drainage. Blue print of the drainage system not available, in case of clogging. Possibility of tissue getting blocked is very high. 4. Basin in the middle does not serve any purpose. 5. Filter system is too complicated.
3	M/s. S.M. Scientific Instruments Pvt. Ltd. Model : SMI-233HAG Make : Jindal	Non Responsive on virtual demonstration and catalogue data.	Responsive	1.Smaller Dimensions (1980 x 975 x 1890) 2. Side safety glass panels is given only as optional in the brochure/catalogue.

S.N.	NAME OF THE FIRM	TECHNICAL EVALUATION	COMMERCIAL EVALUATION REPORT	REASONS FOR NON RESPONSIVENESS
4	M/s. KK ALLIANZE Model : M-GWS Make : Medimeas Instruments,Ambala	<i>Not Demonstrated despite given chance.</i>	Non-Responsive (Quantity of Manufacturing Capacity is lesser - sch.1. 84 & Sch.2. 108)	1) Not Demonstrated. 2) Annual manufacturing capacity of at least 297 nos. is not met.
5	M/s. Yorco Sales Pvt. Ltd. Model : YSI-222EX Make : York	Non Responsive on virtual demo and catalogue data.	Responsive	<ol style="list-style-type: none"> 1. Dimensions L/W/H: 2000 x 1000 x 1900 mm approx. with \pm 10% tolerance are not mentioned in the catalogue. 2. Height adjustable by 2 Electric cylinders from 750 – 1050 mm, programmable for 4 users is not mentioned in the catalogue 3. Side safety glass panels is not mentioned in the catalogue.
6	M/s. SHRI PHARMA ASSOCIATES Model : GWS-700H	Non-responsive on bid-security. As per the tender document ITB Clause 13.3.C - Domestic Enterprises (i.e., from Tamil Nadu) who is the manufacturer of the tendered product within the state and registered with MSME are eligible for EMD Exemption, otherwise not eligible.		