

RESULT OF EVALUATION

ONLINE TENDER FOR FIXING RATE CONTRACT FOR SUPPLY AND INSTALLATION OF SEMI AUTO ANALYSER TO VARIOUS GOVT. INSTITUTIONS

TENDER NO. E934/ANL/RC/TNMSC/ENGG/2023, DT: 15.03.2023

Sl. No	Bidders Quoted	Model/ Make	Responsiveness		Remarks
			Technical	Commercial	
1.	M/s.Transasia Bio Medicals Ltd	Erba Chem5x	Non-responsive	Responsive	As per the specialist report, <ul style="list-style-type: none">• Touch Screen not Available• Built-in-Incubator not Available• RS232 Port not Available All the above 3 requirements are Mandatory and not complied
2.	M/s.Shan Biotech & Diagnostics	Yumizen CA40, Horiba Medical	Responsive	Non-responsive	Despite given change, you have not furnished end user certificate for as non-manufacturer bidder for the supply of equipment for same make of similar model.
3.	M/s.Meril Diagnostics Pvt. Ltd.	CliniQuant, micro	Non-responsive	Responsive	As per the specialist report, <ul style="list-style-type: none">• External Cuvette not available• Touch Screen not available• Built-in Incubator not available• LIMS incompatible• RS 232 Port not available• USB Port not available• Interfacing cable not available• Barcode Scanner not available• 12 digit ID not available All the above requirements are mandatory but not complied.
4.	M/s.Medi	Bonavera	Non-	Non-	As per the specialist report,

Sl. No	Bidders Quoted	Model/ Make	Responsiveness		Remarks
			Technical	Commercial	
	Focus India Pvt. Ltd.	ChemUNO, Beacon	responsive	responsive	<ul style="list-style-type: none"> LIMS incompatible RS232 port not Available Data transfer is very poor and not on real time basis. 12-digit ID not Available <p>All the above requirements are mandatory, but not complied.</p> <p>Commercial point:</p> <p>Despite given change, you have not furnished end user certificate for as non-manufacturer bidder for the supply of equipment for same make of similar model.</p>
5.	M/s.Instuments & Chemical Pvt. Ltd.	LAB INCO	Non-responsive	Non-responsive	<ul style="list-style-type: none"> External Cuvette not available. Touch Screen not available. Flow Cell volume > 20µl. Aspiration volume > 250µl. Built-in-Incubator not available. LIMS incompatible. Interfacing cable not available. Barcode scanner not available. 12 digit ID not available. CE and ISO13485 certificates expired. <p>All the above requirements are mandatory</p> <p>Commercial point:</p> <p>Despite given change, you have not furnished end user certificate.</p>
6.	M/s.Carewell	GB235,	Non-responsive	Responsive	<ul style="list-style-type: none"> RS232 Port not available

Sl. No	Bidders Quoted	Model/ Make	Responsiveness		Remarks
			Technical	Commercial	
	Medical System	Genuine Biosystem			<ul style="list-style-type: none"> 12 PID not available Both the requirements are mandatory for LIMS Functionality, but not available.
7.	M/s.BHAT Bio-tech India Pvt. Ltd.	ARX-199i, Micro Lab make	Non-responsive (Not demonstrated)	Non-responsive	Not demonstrated Commercial point: Despite given change, you have not furnished end user certificate.

No responsive bidder in the tender and hence tender is hereby cancelled.